

3/12



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2818105

TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

No new defects noted in area

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
---------	-------------	-----------------	-------------------	--------------

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	3/17/17
Target Finish:	3/17/17
Actual Start:	3/12/17
Actual Finish:	3/12/17
Report Date:	3/10/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270-#####-0901-#####-#####-####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2818105 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
No new defects noted in area

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		ARABETT				10		N		08:00	00:00	217.36
	AREPAIR		SSELL				10		N		08:00	00:00	212.00
Total Actual Labor:													429.36



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2818105 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
No new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Name A. Rabette S. Sell Date 3-12-17 Page of

(Please Print)

Watchman A. Robette S. Sell WO# 2818105

Inspected From Camden To Linthicum

[illegible]

Item

Comments

No new Defects Noted in Area.

COPY

Were switches in the area inspected?

Yes ☒

No _____

Is this a Special Inspection?

Yes _____

No ✓

Reason for Special Inspection?

[Signature]

Track Inspectors Signature

James Reaver

Supervisory Certification

3/13/17

Date _____

3/13



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2807717 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area.
this work order replaces 2815684

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading
CI: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	3/6/17
Target Finish:	3/6/17
Actual Start:	3/13/17
Actual Finish:	3/13/17
Report Date:	3/3/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2807717 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area.
this work order replaces 2815684

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		ARABETT				10		N		08:00	00:00	217.36
	AREPAIR		SSELL				10		N		08:00	00:00	212.00
Total Actual Labor:													429.36



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2807717 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area.
this work order replaces 2815684

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor



Watchman A. Robette S. Sell

WO# 2818105

Inspected From *Camden*

To Linthicum

[illegible]

Yes ☒

No

Yes _____

No ✓

Robert K. Rife

Track Inspectors Signature

Jamie Reaver

Supervisory Certification

3/13/17

Date _____

Name A. Robette S. Sell Date 3-13-17 Page _____ of _____

(Please Print)

Watchman A. R. Hether S. Sell

WO# 2807717

Inspected From Hunt Valley

To Luther Ville

[illegible]

Item

Comments

No New Defects Noted in Area.

COPY

Were switches in the area inspected?

Yes ☒

No _____

Is this a Special Inspection?

Yes _____

No 4

Reason for Special Inspection?

Res. the R. A. M. C.

Track Inspectors Signature

James Reaver

Supervisory Certification

3/13/17

Date _____

(Please Print)

WO# 2820015

To

Date _____

3/14

omitted
due to
snow
duty



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2820015

TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
3-14-17 Snow duty

Alias:	Location:	CHAIN_MARKER LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	3/16/17
Target Finish:	3/16/17
Actual Start:	3/14/17
Actual Finish:	3/14/17
Report Date:	3/12/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2820015 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
3-14-17 Snow duty

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			ARABETT						N		08:00	00:00	217.36
AREPAIR			SSELL						N		08:00	00:00	212.00
Total Actual Labor:													429.36



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2820015 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
3-14-17 Snow duty

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

(Please Print)

WO# 2820015

To

Item			
------	--	--	--

Comments

SNOW DUTY

COPY

Yes

No

Yes

Date _____

3/31/17

3/18



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2822208 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
03-18-2017

CM 43+89 BWI, #2 track, west rail, U-69 joint, loose bolts, Camp Meade south x-ing
CM 43+89 BWI, #2 track, west rail, U-69 brace, loose bolts, next to U-69 joint with loose bolts
CM 43+90 BWI, #2 track, west rail, Rust line bleeding out of crack where U-69 is welded to x-ing U-69 rail

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:		Year:		Manufacturer:	
Serial Number:				License:	
Service Address:	1155 344 West North Ave, Baltimore MD				

Item	Description	Unit of Measure	Last Reading Date	Last Reading	
CI:					
Mileage Meter:					
Sched Start:		Site:	LTRAIL	Job Plan:	2961
Sched Finish:		Priority:	1	Job Desc:	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
Target Start:	3/22/17	Work Type:	PM	Supervisor:	
Target Finish:	3/22/17	Status:	CLOSE	Lead:	JREAVES3
Actual Start:	3/18/17	Parent:		Owner:	
Actual Finish:	3/18/17	Person Group:	MTA527	Owner Group:	
Report Date:	3/14/17	GL Account:	J05-####-05270-#####-0901-#####-#####-####-#####-000-30-00	Service:	
Reported By:	MTACRON	Warranty Situation Present?	N	Service Group:	
Requestor of Work:		PM Num:	48481	Classification:	2732
				Part Failure:	



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2822208

TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
03-18-2017

CM 43+89 BWI, #2 track, west rail, U-69 joint, loose bolts, Camp Meade south x-ing
CM 43+89 BWI, #2 track, west rail, U-69 brace, loose bolts, next to U-69 joint with loose bolts
CM 43+90 BWI, #2 track, west rail, Rust line bleeding out of crack where U-69 is welded to x-ing U-69
rail

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2822208 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
03-18-2017

CM 43+89 BWI, #2 track, west rail, U-69 joint, loose bolts, Camp Meade south x-ing
CM 43+89 BWI, #2 track, west rail, U-69 brace, loose bolts, next to U-69 joint with loose bolts
CM 43+90 BWI, #2 track, west rail, Rust line bleeding out of crack where U-69 is welded to x-ing U-69 rail

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			GLAM						N		08:00	00:00	210.32
AREPAIR			MPOLLAF						N		08:00	00:00	210.32
AREPAIR			TSCHISLI						N		08:00	00:00	210.32
Total Actual Labor:													630.96



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2822208 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
03-18-2017

CM 43+89 BWI, #2 track, west rail, U-69 joint, loose bolts, Camp Meade south x-ing
CM 43+89 BWI, #2 track, west rail, U-69 brace, loose bolts, next to U-69 joint with loose bolts
CM 43+90 BWI, #2 track, west rail, Rust line bleeding out of crack where U-69 is welded to x-ing U-69 rail

Task IDs								
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

